

In the Drawings:

The attached sheets of drawings show the drawings on a proper page size.

These sheets replace all the original 14 sheets.

Attachments: (14) Replacement Sheets




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5





FIG. 6




FIG. 7





FIG. 8





FIG. 9



INFORMATION PROCESSING APPARATUS





FIG. 10



70

```
PROGRAM MAIN  
COMMON /BLK/X(1000)  
:  
:  
WRITE(6,'(8Z)') X(1)  
END
```


FIG. 11



80

```
PROGRAM MAIN  
COMMON /BLK/X(1000)  
:  
:  
:  
Y=X(1)+1  
END
```

FIG. 12



90

```
PROGRAM MAIN  
REAL A(1000), B(1000)  
DO I=1, 1000  
    A(I)=1.0  
ENDDO  
DO I=1, 1001  
    B(I)=A(I)  
ENDDO
```

FIG. 13




FIG. 14